## National Transportation Safety Board Washington, DC 20594

## **Brief of Accident**

## Adopted 11/06/1998

4	N	C	97	Ľ	۱۲	45	В

File No. 1316	(	09/08/1997	BUCKLAND, AK	Aircraft Reg No.	N1123R	Time (Local): 15:45 ADT		
Engine M Aircra Number Operating C Nam Type of Fligh	Make/Model: aft Damage: of Engines: certificate(s): le of Carrier: at Operation:	Commuter Air Carrie BERING AIR INC.	er; On-demand Air Taxi nestic; Passenger Only Commuter	Crew Pass	Fatal 0 0	Serious 0 0	Minor/None 1 9	
Last Depart. Point:				Condition of Light: Day Weather Info Src: Pilot Basic Weather: Visual Conditions Lowest Ceiling: None Visibility: 10.00 SM Wind Dir/Speed: 090 / 012 Kts Temperature (°C): 11 Obstr to Vision: None Precipitation: None				
	Age:		gine Land; Single-engine Land		Total La:	me (Hours) All Aircraft: 9 st 90 Days: 3	50	
Instrument Ratings Airplane		Т	Total Make/Model: 1000 Total Instrument Time: 1000					

The Cessna 402C, N2649Z, and the Cessna 208B, N1123R, were both parked at the ramp area of a remote airport. Both airplanes had passengers on board, and both airplanes were preparing to depart on charter flights. The Cessna 402C was parked to the right, and slightly behind the Cessna 208B. The pilot of the Cessna 402C began a right turn out of the parking spot. During the turn, the tail of the airplane struck the right aileron of the Cessna 208B.

## Brief of Accident (Continued)

ANC97LA145B

File No. 1316 09/08/1997 BUCKLAND, AK Aircraft Reg No. N1123R Time (Local): 15:45 ADT

Occurrence #1: COLLISION BETWEEN AIRCRAFT (OTHER THAN MIDAIR)

Phase of Operation: STANDING - ENGINE(S) NOT OPERATING

Findings

1. (C) CLEARANCE - NOT MAINTAINED - PILOT OF OTHER AIRCRAFT

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

The failure of the pilot of the Cessna 402C, N2649Z, to maintain adequate clearance while taxiing alongside the stationary Cessna 208B, N1123R.